G. R. S. 59]

GENERAL AND REVENUE SECRETARIAT.

1912
(Miscellaneous)

File No. 378-12

Serial Nos. 1

Papers Filed.

Month July 13

SUBJECT.

Rejection to the Srirambhadra Swamy Temple, Hariharpur

PREVIOUS REFERENCES.	LATER REFERENCES.
4 11	
A/Amanuensis/Record 26/9/13	

RS 11]

1912

GENERAL AND REVENUE SECRETARIAT.

(Miscl)

NOTES.

File No 378-12

File Heading

Repairs to the Sri Mukteswaraswamy temple at Harihar

From

The Deputy Commissioner, Chitaldroog Dt

No 266 Dated 3-1-13. Received 4-1-13

Diary No. 1073 Enclos. 1 file Spare Copies. nil Serial No 1

Brief Abstract of Letter

Submits for sanction an estimate for Rs 173/- for the above repairs

NOTES AND ORDERS.

As this institution has already been included in the general list sent by the Dy Comr in Feby 1912 (which is being dealt with in M.7 488-11), ~~May~~ may this file be simply placed along with that

GPB 3000 2/6 11

Revenue

Secn

File No. 378 of 1912

Serial No.

file for reference, further action being taken in this file after orders have been passed in the general file re distribution of the State grant among the several institutions in the State.?

Subd May be linked with the ?'s considered.

Cyl (139) 11-1-13

14/1/13

A general reply has been given to all Dy Comrs intimating that no funds could be provided from the State grant of 1912-13 for institns

No funds could be spared for this institn from the State grant of 1912-13. A general reply has been given in M 7 488-11 informing the Dy Comrs that no funds could be provided for this & some other institns

May this be filed for the present? Subd for orders

Cyl (139) 19/1/13

File

Ker

19/1/13

NOTE—Contn sheet.

GPB—65,000—17-6-12

1 R 19 13
ION Bruce
FILE No. 3787
SERIAL No.

From 1912.

The Deputy Commissioner,
Chitaldrug District.

To

The Secretary,
Genl & Rev. Depts. (Mysore)
Bangalore.

Dated

Despatched 3rd Jany. 1913.

Received

General No. 266
No.

Enclosure No. File.

Submitting for sanction an estimate for Rs 178/- for repairing the Mukteswara Swami temple at Harihar

GPB—50,000—26 9 12

Office of

Chitaldrug

Dated Chitaldrug, 2nd January 1913.

From

K. Krishna Iyer Esquire,

Officiating Deputy Commissioner,

C h i t a l d r u g.

To

K. R. Srinivasiengar Esquire M. A.,

Officiating Secretary to the Government of

His Highness the Maharaja of Mysore,

General and Revenue Departments,(Muzrai),

B a n g a l o r e.

I R,

With reference to your letter No. 835/Muz,F. 17-11-2 dated the 16th October 1911 stating that application for the sanction of the estimate for Rs 173/- for repairing the Muktesvaraswamy temple at Harihar, may be renewed in February 1912, I have the honor to invite your kind reference to the statement sent with this office letter No. 361 dated the 17/20th February 1912 wherein this work has been included and to request that the estimate submitted therein may kindly be sanctioned.

I have the honor to be,

S I R.

Your most obedient servant,

Offg: Deputy Commissioner,

Chitaldrug District.

S.V.

Cake

probable Cost among outhouse side portions of the Temple in Ramapuri at Harihar Estd 378-12-1

Details of work	No	Dimension			Contents	Total
Removing and replacing the Stone slabs over the roof	1	12½	5	.	62	
Total Sq: ft	.	.	.	.		62 S. ft
Removing and replacing the Superstructure	1	13	10	7/2	455	
do —— the base ment	1	15	5	2	150	
Total C. ft					605	C ft
New Stone work						
Stone Slabs for the roof in front of the building	1	24	3	.	72	
do —— over Verandah	1	5 4/2	1 3/4	.	9	
do —— over Kattle	2	8	5	.	80	
Total Sq: ft					161 S. ft	
Concrete flooring						
over the roof	1	12½	5	4"	21, c. ft	
Total c. ft	.	.	.	.	.	21 c. ft
Chunam plastering						
for the parapet over the roof	1	4 3/4	.	3	14	
	1	4 3/4	.	1 3/4	8	
	1	12½	.	3	37	
	1	12½	-	1 3/4	21	
	2	4 3/4	.	4	38	
Total S. ft					118 S. ft	
Earth Collecting and removing	.	L S.				

Abstr.

Items	per	Rate	Quantity	Amount
old Stone work over the roof	Sqs:ft	6 .	62,5.ft	23 . .
do ——— basement etc	1C.ft	.	605 C.ft	75 . .
New Stone work	Sqs:ft	4 .	161,5.ft	40 . .
Concrete work	C.ft	3 .	21 C.ft	4 .
Chunam plastering	per	8 .	1.18	3 . .
Earth work	LS			20 . .
Contingencies at 5%.				1

Total Rupees 17

Rupees one hundred and seventy three only

K. Hanumantharao
Sanitary Inspector.
20-7 11

S. Sundaram
Deputy Amildar.

Deputy Tahsildar

Extract from the Inspection Report of the Muzrai Institutions at Harihar by Mr. K Krishna Iyer, Senior Asst. Comr. Davangere Sub Division on 4th June 1911.

Mukteswara temple in Bramhapure, Harihar.

"Mukteswara Swamy temple is a neat little one, constructed in very ancient times. An Aswatha tree has rooted itself on the roof of on its South west Corner and is damaging the walls. and in the Same Corner the foundation is also probably sinking. If prompt steps are not taken I am afraid the walls may come down. The Dharmadarsis informed me that an estimate for its repairs had been prepared and Submitted some years ago but no Sanction has yet been

Mukteswara

Obtained. It is very necessary to have the damaged wall removed and rebuilt out of provincial Anjuroi grants as the same is a Anjuroi institution

The Deputy Amildar has been directed to get up a fresh Estimate and submit the same to the Deputy Commissioner through this office at as early a date as possible.

(Sd) K. Krishna Iyer.
SDO.

"True Extract"

K. Krishna Iyer
SDO

ಸಂ. ಕ-649/ಕ-13.

ಸಂಖ್ಯೆ 72
28-7-11 ರಲ್ಲಿ

ಕಛೇರಿ ದಿನಾಂಕ 24.7.11

ಸ್ವೀಕೃತಿ ಪತ್ರ

ಶ್ರೀ ಎಸ್. ಸಿದ್ದಲಿಂಗಪ್ಪ
ಅಮಲ್ದಾರ್

Bangalore
21-8-11

196

2-8-1911

Yours

I am sorry I cannot accept your invitation for dinner on the 3rd as I am leaving Bangalore on the 1st for Mysore and shall be there for a week. I am sorry I cannot accept your invitation for dinner on the 3rd as I am leaving Bangalore on the 1st for Mysore and shall be there for a week. I am sorry I cannot accept your invitation for dinner on the 3rd as I am leaving Bangalore on the 1st for Mysore and shall be there for a week.

I. Somasundaram

Dy Secretary

1.8.11

216

12-8-1911

Yours

Thanks for your letter of the 11th inst. I am sorry I cannot accept your invitation for dinner on the 3rd as I am leaving Bangalore on the 1st for Mysore and shall be there for a week. I am sorry I cannot accept your invitation for dinner on the 3rd as I am leaving Bangalore on the 1st for Mysore and shall be there for a week.

S. Ramachandra Rao

Dy Secretary

12.8.11.

ಶಿರೇ
5
7-7-11

ಸಂಪಾದಕರು ಕನ್ನಡಪ್ರಭ

ಸರ್ ನಿಮ್ಮ ಪತ್ರಿಕೆಯಲ್ಲಿ ಪ್ರಕಟವಾದ ವರದಿಯ ಬಗ್ಗೆ —

ವರದಿಯಲ್ಲಿ ಸಾಮಾನ್ಯ ಜನರಿಗೆ ಅರ್ಥವಾಗದ ಪದಗಳನ್ನು ಬಳಸಿರುವುದರಿಂದ
ನದಿಯ ದಡದಲ್ಲಿ ಮಣ್ಣಿನ ದಿಣ್ಣೆ (roof) ಕುಸಿಯಲು ಆರಂಭವಾಗಿದ್ದು
ಸಾರ್ವಜನಿಕರಲ್ಲಿ ಭೀತಿ ಉಂಟಾಗಿದೆ ಎಂದು ಅರ್ಥೈಸಲಾಗಿದೆ
ಸಲಹೆ ಆಯೋಗದಲ್ಲಿ ಇರುವುದಿಲ್ಲ ಎಂದು ಮಾತ್ರ ಹೇಳಲಾಗಿದೆ
(foundation) ಕಲ್ಲು ಭದ್ರವಾಗಿ ಸಂಪೂರ್ಣವಾಗಿ ಇರುವ
ಆಧಾರದಿಂದ ತಳಪಾಯ ಎಂದರೆ ಅರ್ಥವಾಗುವುದು ಕಷ್ಟ ಹಿಂದಿ
ಕಳ್ಳಸಾಗಣೆ ಪದಕ್ಕೆ ಬದಲಾಗಿ ಅಕ್ರಮ ಸಾಗಣೆ ಎಂದು ಬಳಸಿದ್ದಲ್ಲಿ ಹೆಚ್ಚು ಸೂಕ್ತ
ಎಂಬ ಅಭಿಪ್ರಾಯ ನನ್ನದು

6-7-11

ಎಸ್ ಸೌಮ್ಯಾನಾರಾಯಣ
ವಕೀಲರು Amicus for

ಪತ್ರಿಕೆ 20.7.11

ಸ್ಥಳೀಯ ಅಂಶಗಳನ್ನು ಪ್ರಸ್ತಾಪಿಸಿಲ್ಲ, Report accompanying the estimate ನಲ್ಲಿ ಪರಿಸರ ಅಂಶಗಳನ್ನು ಚರ್ಚಿಸಿದೆ.

ಡಿ ಸುಬ್ರಮಣ್ಯ ಅಯ್ಯರ್
ಸಂಪಾದಕರು

ಸಂ
ಪ್ರ
20.7.11

ಸಂ
6-29
79

ಸಂ
24/7/11

Cost of repairing the Southern side portion of the Muktesvara Swami at Hanchar:

Details of work	No	Dimensions L	B	D	Contents	Total
old Stone work						
Removing and replacing the Stone slabs over the roof	1	12½	5	.	62	
Total Sq: ft	.	.			.	62 Sft
Removing and replacing the Superstructure	1	13	10	7/2	455	
do ——— the basement	1	15	5	2	150	
Total C. ft					605 C. ft	
New Stone work						
Stone Slabs for the roof infront of the building	1	24	3	.	72	
do ——— over Verandah	1	8½	1¾	3"	9	
do ——— over Kattle	2	8	5"	3"	80	
Total Sq. ft					161,8 ft	
Concrete flooring over the roof	1	12½	5	4"	21	
Total C ft					21 C. ft	
Chunam plastering for the parapets over the roof	1	4¾	.	3	14	
	1	4¾	.	1¾	8	
	1	12½	.	3	37	
	1	12½	.	1¾	21	
	2	4¾	.	4	38	
Total S. ft					118,8 ft	

Cost of collecting and removing L S.

Abstract

Items	per	Rate		Quantity	Amount		
old Stone work over the roof	Sq.ft	. 6	.	62,5sft	23	.	.
do ——— basement etc	1 cu:ft	. 2	.	6052.ft	75	.	.
New Stone work	Sq:ft	. 4	.	161,8.ft	40	.	.
Concrete work	c.ft	. 3	.	21 c.ft	4	.	.
Chunam plastering	per square	2 8	.	1.18	3	.	.
Earth work	LS				20	.	.
Contengencies at 5%.	-	- -	-	-	8	.	.
Total Rupees	.	. .	.	-	173	.	.

Rupees one hundred and Seventy three only

K. Hanumanta Rao
Sanitary Inspector
20 7 11

S. Soundararajan
Deputy Auditor.

Countersigned for rupees one hundred and Seventy three only

Officg Dy Commrs
5/9/11. Executive Engr